

"BORGFRED"

Nwc. 109361.

It is submitted the Owner's Agents be informed that when the vessel left Cardiff in November, 1951, the class was subject to the LP cylinder repair being examined before the end of 3,52.

The Special Survey of the machinery, due 4,52, had been partly held and to complete this survey for record of LMC S 10,51 all rule requirements remained to be carried out except:-

Examination of-sea connections;
Crank thrust and intermediate shaft;
Condenser and water end of circulating pump.

Wd
2-14
14.5.52.



© 2021

Lloyd's Register
Foundation

009848-009859-0093