

X  
COPY

# Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

Enclosures.

18th May, 1948.

Dear Sirs,

S. I have to acquaint you that the case of the Steamer "CYRUS SEARS" has recently received consideration in connection with the survey carried out by the Society's Surveyors at Sunderland in March/April last.

As a result of this inspection the vessel has been classed "100A1" subject to repairs to keel and bottom shell plates, etc., (p & s) at the first convenient opportunity and to the ribs in way of top port in the L.P cylinder, found fractured and repaired, being re-examined by the end of April 1949; also to automatic feed water regulators being fitted.

Notations of S.S.Sld.-4,48 and LMC 4,48 have been assigned in respect of the Special Survey of hull and machinery, for which Classification Certificates are enclosed herewith.

In view of the Screwshaft Survey carried out by the American Bureau in January 1946 the next Screwshaft Survey becomes due in January 1949.

I have also to inform you that owing to the omission of cement the bottom under the boilers will require to be examined internally annually.

Yours faithfully,

Clerk to the  
Classification Committee.

Messrs. Stephenson Clarke Ltd.,  
4, Fenchurch Avenue,  
London, E.C.3.



© 2021

Lloyd's Register  
Foundation