

Engine No. 25236 Made by Sulzer Bros Ltd.  
 or De Haan + Oordman' Rad N°. 250.

WINTERTHUR Report No. 263.

It is submitted that ~~a copy of~~ this Report be  
 forwarded to the ROT. Surveyors for their  
 returned guidance and for completion.

Rot  
 you should be  
 ed to the Secretarys  
 dated 14/4/48  
 the size of shaft in  
 1,500.2.47. appeared  
 differs from ~~that~~ <sup>those</sup> in this report.

*Satisfactory  
 Reply. 9.5.  
 7.10.48.*

Date 12-6-48.

*Copys. Rot-  
 22.6.48.*

They should be asked to make the size of  
 the line shopping fitted.

documents as are required to the Surveyors concerned

NY Med  
~~The Potomac~~  
~~should be added~~

9.5  
7.10-48



© 2021

Lloyd's Register  
Foundation