

"OTTAWA MAYCLIFFE"

F.E. Rpt: Mtl No: 6906

It is submitted before this case receives consideration, the MONTREAL Surveyors be referred to previous correspondence and requested by cablegram to furnish the service limits as proposed by the Owners for this vessel and to state whether the bottom in way of the boiler space has been cemented as required by the Rules.

They should be informed by letter it is concluded a Shelter deck stringer angle of  $2\frac{1}{2}$ " x  $2\frac{1}{2}$ " x  $\frac{5}{16}$ " has been fitted, as indicated on the approved and as built midship sections, but this should be confirmed.



© 2024

J.C.D.  
2.10.46

Lloyd's Register

Foundation

009879-009887-0032