

First date 23rd July Last date 31 July '57

Last Report (For Head Office only)

W 1000 W 1010 W 110

32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

Table with 4 columns: PROPULSION, PORT, STARBOARD, and AUXILIARY EQUIPMENT. Rows include Generators, Exciters, Air Coolers, Motors, Air Coolers, Control Gear, Cables, etc., Insulation Resistance, Insulating Oil Test, Overspeed Governors, Magnetic Couplings, Air Gap, and Auxiliary Equipment items like Generators & Governors, Motors, Switchboards & Fittings, Circuit Breakers, Cables, Insulation Resistance, Steering Gear Generators and Motors, and Navigation Light Indicators.

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN
AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to Sat. Spt.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main
Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

LEAVE THIS SPACE BLANK

Survey fees ... Rp. 200.--

Damage fee ...

Expenses... ..

Date when A/c rendered

It is submitted that this vessel is eligible to remain as CLASSED.

24/10/57

