

4m,4,59

8 MAY 1959 ^{4E}

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME..... TRITON MARIS


REPORT.....

Hav. 10025
Rot No. 47154

ABS due 4.59, now held.

Docking. Some ice damage sustained to propeller and propeller blade tips satisfactorily repaired. The tailshaft drawn and examined, found cracked circumferentially at top of cone, and new spare shaft satisfactorily fitted.

IT IS SUBMITTED this vessel is eligible to remain as classed, with fresh records of ABS 3.59 and TS (CL) N 4.59



4.5.59



© 2021

Lloyd's Register
Foundation

009896-009903-0129

