

COPY

BELONGS TO  
ROTTERDAM REPORT NO.

# LLOYD'S REGISTER OF SHIPPING 54201



Port of ROTTERDAM

11th July, 1962

*This is to Certify that I have*

*Surveyed the Machinery of the s.s. "MEDINA PRINCESS", 7069 tons gross of Leith, whilst lying afloat at this port on the 19th June, 1962 and subsequent dates for wear and tear repairs. . . . .*

*and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will **Recommend** that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book*

*and that her Machinery Classification Record be continued in the Book, subject to any outstanding conditions attached to the machinery class being dealt with as previously recommended.*

Parts now examined: (C.S. Items only)

*H.A. Schippers*

Engineer Surveyor to Lloyd's Register.  
H.A. Schippers.

## KEY TO ABBREVIATIONS

|     |  |        |                                   |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book published by the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or for any other Officers or Agents of the Society."

© 2021

Foundation

009896-009903-0318