

LLOYD'S REGISTER OF SHIPPING

6461



Port

Bremen

17th June, 1962

This is to Certify that I have

surveyed the Machinery of the S/S "MEDINA PRINCESS" 7069 tons gross
Leith, whilst the ship was lying afloat in Bremen on the 30th
May, 1962 and subsequently on account of repairs (wear and tear)

we shall
that I ~~will~~ transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that ~~all~~ the following ~~were~~
recommendations made by ~~and~~
in connection therewith have been carried out to my satisfaction; also
we shall
I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

that her Machinery Classification Record be continued in the Book.,
without fresh record of survey, subject to the fire extinguishing
being placed in good condition, the emergency fire pump being
placed in good condition, the lagging on the boilers being satis-
factory restored, the generators to be cleaned as necessary, the
terminals of the outer generator to be overhauled and the earth faults
on the outgoing cables from the switchboard
being dealt with, the lighting in the U.R. and
B.R. to be permanently restored and all tem-
porary lighting to be removed or made per-
manent at Rotterdam to which port the ship is
now proceeding direct from Bremen

is now examined:

Q.S. Items only) X

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book
or publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof,
Surveyors, or other Officers or Agents of the Society."

B.1.) 150m,5.60 (MADE AND PRINTED IN ENGLAND)

009896-009903-0324

© 2021

Lloyd's Register
Foundation