

'GRANDYKE' - Nwc. Rpt. No. 106975

Before this case receives consideration ^{IT IS SUBMITTED} the
Surveyors should be referred to Circular No. 1707A which
reads as follows :-

"Welding repairs required to be periodically examined
for two years.
Fractured stern frames; mainpiece of rudders, shaft
brackets, engine seats, shell plates and strength
decks."

They should therefore be requested to state
^{their recommendation for}
their reasons for the deletion from the special conditions
of class of 'sternframe solepiece (E.W. 9.48)'.

Write Nwc :- 24/3



© 2021

Lloyd's Register
Foundation

009896-009903-0339

g.e.
7.3.50