

4E
F10 FEB 1959

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... BRISSAC..... REPORT..... Nnt. No. 737

MBS due 1.59 now held.

Docking.

C.S. Advanced. Steam pipes examined.

The inboard turbo generator ^{gearing} ~~cracked~~, renewed,
tested under working conditions found satisfactory;IT IS SUBMITTED that this vessel is eligible
for the record MBS 1.59. SPS 1.59.© 2021
52.59.Lloyd's Register
Foundation

009904-009911-0024