

by Chief Ship Surveyor

"BRUNSWICK"

Received from Chief Ship Surveyor

15 MAR 1934

EL'S NAME

*now named
S.S. 'ALDAN'*

Rpt.

Rot

No. 22747

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

e of Survey

COMPLETION OF *2nd* S.S. No. 2 (due 5-32)The *2nd* S.S. No. 2

partly held at

*Rotterdam*now completed, and the following repairs done (due to *wear & tear*) :-*Vessel placed on a slipway, bottom coated, minor repairs effected.**13 lengths of chain cable supplied to replace chain cable worn below the Rule limit.*

It is submitted the vessel is worthy to remain as classed, with record of Survey *3.34* and notation of *S.S. No 2-32* as recommended.

*100A1**3.34 Rot**S.S. Rot No 2-32**W.H.G.**[Signature]**14.3.34*

© 2021

Lloyd's Register
Foundation

009904-009911-0124