

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

M.H. 'Brunswijk' Rpt. Rot

No. 7013

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

03. 92

Depth "d"

18' 9"

Framing: Table No.

Page 11

Description

Bulb angle

Longitudinal No.

18370

Proportions

 $\frac{\text{Length}}{\text{Depth}} =$

9.9

Bridge Deck Sheerstrake

as per rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A-1. (stat) as recommended.

 \pm 100A-1. (stat)

1 Dr (stat)

NB. See DBa 84 x 3/8 f 120 5896 APT 686

FR. Immediate bulkhead in fore hold damaged with 'HBH only' beam A & C PDI 872 F33

