

N.N. GASCOYNE

B.C. CLASS

(Received at London Office)

No. BC 290

Rpt. 8.

# REPORT OF SURVEY FOR REPAIRS, &c.

10627  
1950  
26495

Date of writing Report 19... When handed in at Local Office 19... Port of Keith, S. Georgia

No. in Survey held at Keith, S. Georgia Date, First Survey 10 Last Survey 10 1949

on the Wood, Iron or Steel SS Southern Breeze (No. of Visits...)

Built at Vegesack By whom Bremer Vulkan When 1936 6

Owners' Address The S. Georgia Co. Ltd. Owners' Address (If not already recorded in Appendix to Register Book)

Managers W. Salvesen & Co. Port belonging to London

at or in Dry Dock? at Name of Dock Port No. 291 Port B.C.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Machinery and Boiler Surveys
* for Special Survey.	(Including date of N.B., if any).
Date of last Survey and of Periodical Surveys.	
<u>BS 10/48</u>	<u>MBS* 10/46</u>
<u>purpose 10/48</u>	<u>BLS 7/48</u>
<u>SS LK SR 10/46</u>	<u>MSP 7/46</u>
<u>AS 10/48</u>	<u>CL 5/48</u>
<u>Fitted for oil fuel</u>	
<u>for now in ice.</u>	

Alterations in the existing records should be underlined.

Where the Surveyor has not made a special damage report he is required to state whether he has made a special damage report and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

RECOMMENDATIONS AS PER RULE, FOR

Date

10-10-49

DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
... ..								
... ..								
... ..								

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Openings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
In way of sidelights	Rudder	Scuppers	Boats
...	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
...	Windlass	Hatches	Condition, how ascertained
...	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
...	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
...	Have Watertight Doors been examined and found efficient?	Treenails	Anchor, No. of
Plating	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
...	Air and Sounding Pipes	Transoms, Pointers & Crutches	length mean diamr.
...	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
...		" " at other places	Rule length size
...		Stringers, Clamps & Shelves	Chain Locker
...		Salting	Hawsers & Warps
...		State if examined.	Standing and Running Rigging
...			Sails

Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

G. Hansen  
Surveyor to the British Corporation

Section 29	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)				19
Travelling Expenses (if chargeable)				19
Second Surveyor's Fee (if any)				

Committee's Minute WED. 22 MAR 1950

Character Assigned 6.49 Keith S. Georgia  
with 2. Bergen  
as 10.49 BC 29.49



Insert Character of Ship and Machinery precisely as in the Register Book.

Is Certificate required? If so, to be sent to