

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"LISS"

REPORT

Cco.

No. 4145.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH fire.

All valves on top of port boiler overhauled. Temporary repairs effected to main stop valve and safety valves and the Surveyor recommends that the port boiler safety valve spindles and the main stop valve be renewed by 10.53.

Electric circuits in engine room and stokehold repaired or renewed as required.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as recommended.



© 2021

Lloyd's Register
Foundation

11.9.53.