



Lloyd's Register of British & Foreign Shipping,

Collingwood Buildings, Newcastle-on-Tyne.

LLOYDS REGISTER,
LONDON.

REC'D 31 AUG 1909

ANSP

Reference

S

The Secretary
London.

Sir,

With reference to the enquiries
contained in your Cassing Letter of
the 27th inst. regarding the
S.S. "Eruption Coast", Report No. 57167.
I can not quite understand the
question regarding the framing for
one-fifth length at the after end.
The main framing is $11 \times 3\frac{1}{2} \times 2\frac{1}{2}$ to $\frac{1}{20}$ bulb
angles & the frames in way of double
bottom are $3\frac{1}{2} \times 3\frac{1}{2} \times 9\frac{1}{2}$ to $\frac{1}{20}$ angles as
stated in the first Cassing Report.

Yours faithfully

W. S. S. S.
W. S. S. S.

009954-009961-0227

spacing

Centre line bulkhead

Deck. Material and thickness

Forecastle Deck Stringer Plate, b'dth

Angle on ditto

Referred to the Chief Ship Surveyor.

AL

AUG 31 1969

RBM



© 2021

Lloyd's Register
Foundation

Receipt
SEL
The re