

m, 8, 21.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "Elaine Llewellyn" Rpt. Abn, No. 13196

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Transverse No. 61.5

Depth "d" 18.0 to upper dk
22.0 to R. G. dk.

Framing: Table No. 3

Description Bulb angle

Longitudinal No. 17220

Proportions Length = 13.33 to upper dk.
Depth = 11.20 to R. G. dk.

Upper Deck Sheerstrake as approved.


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100 A1 (Steel)

1 DK (Stl)

Cell D/B 235' 500t F.P.T. 48t APT 68t.

FK 4BH Cem. Lloyds A+C/P P 18' 984, 1367, F 23'.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

09994-01003-0114