

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

12 FEB 1948

VESSELS NAME "FORT STAGER"

REPORT nwc.

No. 105000

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

The class is subject to permanent repairs to indented shell plates (p & s) at the first convenient opportunity and to (a bower anchor and 45 fathoms of chain cable being supplied and to 2 bower anchors and stream anchor on board being submitted to the Statutory Test).

The NEWCASTLE Surveyors report the vessel placed in dry dock, bottom coated, a General Examination due 2.48 held and minor repairs effected.

Indented shell plates as above specially examined and continue efficient meantime.

IT IS SUBMITTED the vessel is eligible to remain as classed with record of docking survey 12.47 subject as above and to have the notation "Examined 12.47" valid for 12 months, as recommended, assigned.

12.47 Shl. subject

Examined 12.47.



© 2021

Lloyd's Register
Foundation

009994-010003-0149