

"EL KARIM"

Msl. 11430.

Msl. 11429.

Before this case receives consideration, SUBMITTED
the Marseilles Surveyors be informed as follows:-

- 1). The information given in the Makers' letter regarding Torsionals (forwarded with this report) is not sufficient. To enable a proper investigation to be made, please arrange for the actual torsionograph records to be forwarded here together with particulars of the magnification of the records and calculations of the stresses.
-). With reference to First Entry Report No. 11430:-
 - (a) Please state whether these new engines have been built under L.R. survey.
 - (b) Please state the identification marks on the crankshafts and forward the usual Forging Reports thereon.
-). It is noted from ^{your} Report 9 that nothing has been done towards the Special Survey of the machinery on this occasion and the Owners should, therefore, be asked to give a definite date when this will be carried out, it being noted the Special Survey on the hull is now complete.

End

1.5.53.



© 2021

Lloyd's Register
Foundation

010004- 010011-0020