

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "EL KARIM" REPORT Msl. No. 11429

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

All E.W. construction.

A SPECIAL SURVEY (B) became due 3,52 and was largely held Csb. 3,52.

ACTION and NOTATION of 'ss. Csb. 3,52' DEFERRED for completion of Special Survey.

The ship has previously been reported by the Lloyd's Agents' Surveyor at Casablanca - refer letter dated 17.10.52, to have fractured in way of the welds between the transverse channels.

After consideration in this Office the Lloyd's Agents Casablanca were advised (refer letter dated 31.10.52) that the Owners should consider the advisability of fitting general structural reinforcement to deck and bottom shell plating.

In reply the Owners advised (refer letter dated 17.2.53) that they had decided not to fit the reinforcement suggested and the Marseilles Surveyors were requested to give special attention to the points raised in letter dated 31.10.52 and report whether further fractures have developed - refer letter of 5.3.53.

The MARSEILLES Surveyors report (2,53), this tanker examined in dry dock, bottom coated and the outstanding requirements of the SPECIAL SURVEY (B) commenced Csb. 3,52 complied with.

The Surveyors also report several welds between transverse channels fractured and now E.W. and recommend same to be specially examined next drydocking.

IT IS SUBMITTED ship is worthy to remain as classed, with record of docking 2,53 and Notation of 'ss. Csb. 3,52' subject to the welds between the transverse channels being specially examined next drydocking.

2,53 Msl.) Subject
ss. Csb. 3,52.)
MR. F.C. COCKS.

C.S.S. Records Dept.

to note.

Fractures in welds between transverse channels.



© 2021

Lloyd's Register
Foundation

010004-010011-0023