

COPY.

Food Fishing Vessel "ALEKSY"	Annual Classification Survey due 9,48 Intermediate Machinery Survey due 9,49 Screwshaft Survey due 9,50.
" " " "HILARY"	Annual Classification Survey due 3,48
" " " "JANUARY"	Annual Classification Survey due 7,48 Intermediate Machinery Survey due 7,49. Screwshaft Survey due 7,50.
" " " "KSAWERY"	Annual Classification Survey due 4,49 Intermediate Machinery Survey due 4,50.
" " " "WALERY"	Intermediate Machinery Survey due 5,49 Screwshaft Survey due 5,50.
Steam Trawler "MERKURY"	Special Survey due 4,50 Boiler Survey due 7,50 (partly held 4,50). To complete for the record B.S. 4,50 the safety valves remain to be adjusted.
" " " "HAROCZ"	Boiler Survey due 1,50 (partly held 3,50). To complete for the record B.S. 3,50 the star-board boiler remains to be examined throughout with as necessary by 12,50.
Food Fishing Vessel "NEPTUNIA"	The fore-castle side planking (stbd side) requires to be specially examined and dealt with as necessary by 12,50.
" " " "METR. WELIKY"	The port main engine M.P. column and the aft fan engine bedplate and entablature required to be examined by 5,50. Boiler Survey due 11,50.
S. "PILOT 50"	The main engine fuel pump required to be examined under working conditions after repairs
Steam Trawler "POKUCIE"	Special Survey due 8,50 (partly held on machinery 4,50 by the examination of all main engine valves and casings, crank and thrust shafts and bearings. Boiler Survey due 7,50.
" " " "POLESIE"	Special Survey due 5,50 (partly held on machinery 3,50 by the examination of the main engine in its entirety and the thrust shaft and bearings. Screwshaft Survey due 4,50.
S. "MEGA"	Permanent repairs were required to main engine seating by 7,50. Boiler Survey due 6,50 (partly held 2,50 by the examination of the safety valves and other mountings.
Steam Trawler "WULKAN"	Indented No.1 sheerstrake plate (stbd. side fwd.) requires to be specially examined and dealt with as necessary by 12,50.



© 2021

Lloyd's Register
Foundation

01004-01001-0142