

COPY.

# Lloyd's Register of Shipping.



Port Kobe.

580

31st August 1934.

CERTIFICATE No. 4031.

This is to Certify that

K. Kishigami.

the undersigned Surveyor to this Society did at the request of Messrs. Mitsubishi Denki Kaisha, Ltd., Kobe, attend at their Works on the 9th April 1934 for the purpose of examining and testing under working condition, One set of Compound Wound, direct current motors and generator for Windlass, intended for the vessels, Nos. 580-582, now being built by Messrs. Mitsubishi Jukogyo Kaisha, Nagasaki Works.

		<u>Volts.</u>	<u>Amperes</u>	<u>R.P.M.</u>
36 K.W. Motor	(No. 11150) of	220	by 186	at 1500
31 K.W. Generator	(No. 11129) of	180	by 307	at 1500
60 K.W. Motor	(No. 11125) of	220	by 307	at 650

These motors and generator with their control boxes were submitted to the following running tests of short time rating respectively:-

Full load test of one hour duration.  
100% overload test of one minute duration.

The rise of temperature was measured by thermometers and on completion of the trial, high voltage test and megger test were carried out and all found in good condition.

For the purpose of identification the motors and generator have been stamped as follows:-

<u>Mach: No. 11150</u>	<u>Mach: No. 11129</u>	<u>Mach: No. 11125</u>
: LLOYD'S : : No. 4031 A R : : K.K. 9-4-34 :	: LLOYD'S : : No. 4031 B R : : K.K. 9-4-34 :	: LLOYD'S : : No. 4031 O R : : K.K. 9-4-34 :

Fee,.....¥90:00  
Expenses,.....¥ 5:00

ASSIST. SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

machinery herein described has been constructed under Special Survey in

the Rules and approved plans. The material and workmanship

has been tried under COPY. Road, overland and governor

when connected to this generator: parallel running tests  
run out and all found satisfactory and reliable in my opinion

# Lloyd's Register of Shipping

have been shipped to Nagasaki Works, Meiji  
Hankou, where it is intended to install them on the

31st August 1934



GENERATOR No. 4071

This is to Certify that

K. Kishigami

the undersigned Surveyor to this Society did at the request of Messrs. Mitsubishi Dock Works, Ltd., Kobe, attend at their Works on the 27th April 1934 for the purpose of examining and testing under working conditions, one set of compound wound direct current motor and generator for windlass, intended for the vessel, No. 280-282, now being built by Messrs. Mitsubishi Dock Works, Nagasaki Works, Japan.

36 K.W. Motor	(No. 11150) at 220 by 138 at 1500
51 K.W. Generator	(No. 11151) at 180 by 207 at 1500
60 K.W. Motor	(No. 11152) at 220 by 207 at 650

These motors and generator with their control boxes were submitted to the following running tests of short time rating respectively:-

100% overload test of one minute duration.  
Full load test of one hour duration.

The rise of temperature was measured by thermometers and on completion of the trial, high voltage test and megger test were carried out and all found in good condition.

For the purpose of identification the motor and generator have been stamped as follows:-

Mach: No. 11150	Mach: No. 11151	Mach: No. 11152
: LLOYD'S	: LLOYD'S	: LLOYD'S
: No. 4071 A	: No. 4071 B	: No. 4071 C
: K.K. 9-4-34	: K.K. 9-4-34	: K.K. 9-4-34

Expenses..... ¥ 7100  
Fee..... ¥ 90100

*K. Kishigami*

*R. Buchanan*

ASSIST. SURVEYOR TO LLOYD'S REGISTER

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, detail or negligence of the Committee or any Member thereof, or Surveyors, or other Officers or Agents of the Society."

© 2021

Lloyd's Register Foundation

975. 010004-010011-01010  
9/21/1934