



Lloyd's Register of Shipping.

Outdoor Surveyors' Office,

14, Trinity Square, London, E.C.3.

RECEIVED

31 AUG 1949

30th August, 1949.

Please address
all other communications
on this subject to
THE SURVEYORS.

ANSD.

Dear Sir,

With reference to the Classing Letter of the 23rd instant, regarding the "GADSDEN" (London Report No. 118437), Mr. Greenhalgh states that the cement on the bottom was found adhering satisfactorily to the plating, and it was therefore not considered necessary to drill the bottom shell plating.

Yours faithfully,
THE SURVEYORS,

Per:

M. W. Ambrose

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

010004- 010011- 0269

1/3

Referred to Mr. Perris

[Handwritten signature]

[Handwritten signature]



© 2021

Lloyd's Register
Foundation

Nature of Survey

THICK

RAKE.

SHEER

LE

take below

STRAKE

e below

"

"

"

"

"

"

"

"

"

"

"

(CL)

elc

dry
with

so that