

SHIP'S NAME "GARDEN"

Report LONDON No. 118437

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in 20th of an inch.

STRAKE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.	
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.			
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.
DECK STRAKE																	
below																	
DECK STRAKE32	7	7			.32	7	7			.32	7	7				
below32	7	7			.32	7	7			.32	✓	✓				BADLY FITTED. RENEWED P. & S.
.....	.32	7	7			.32	7	7			.32	✓	✓				" " CROPPED & PART RENEWED P. & S.
.....																	(THE INNER WALL WAS DRILLED P. & S. & FOUND SATISFACTORY)
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....																	
.....								</									

Drillings at ends to be made in the vicinity of the peak bulkheads.

010004-010011-0274

Lloyd's Register
Foundation