

by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

EL'S NAME

Rugeley

Rpt.

Sld

No. 31780

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee,

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22).

Type of Engine

Oil Engines 2 S.C.S.A.

3cy. $20\frac{1}{2}$ " - $8\frac{7}{8}$ "

If Boilers fitted with forced draught

no main boiler

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of

approved type

no.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ h.u.c. 2.36.

2.D.B. 12016.

Y.Mur

28.2.36

It is Submitted the Surveyors be requested to forward in this & all similar future cases the Certificates of tests for the electrical generators

Lv Sld 2/3/36
28/2/36



© 2021

Lloyd's Register
Foundation

010012-010023-0261