

6th September, 1957.

MONTREAL

RMC.11711, 17 - As recommended.

11639 "CANADIAN LEADER" As recommended. It would appear that in addition to the items noted on the Rpt. 8 for completion of the Special Survey that there should be added:-

Examination of steering gear (main and auxiliary)
windlass and pumps,

but confirmation is desired.



© 2021

Lloyd's Register
Foundation