

VESSEL'S NAME Steel S.S. "TAIKOO WAN YI". Rpt. Mdb. No. 10410

Transverse No. 72

Depth "d" 20.7

Framing: Table No. 3

Description Bulb angle as approved.

Longitudinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.03}{\text{Depth}}$

This vessel is stated to have been built in accordance with the plans for the "C" type Standard Vessel, but not under the inspection of the Society's Surveyors.

She has now been examined as far as practicable afloat and completed, and the scantlings and arrangements found to be as approved and the workmanship satisfactory.

The material has been tested by the Surveyors to the British Corporation and copies of the advice notes issued by them have been examined.

The double bottom and fore and after peak tanks have also been tested by the Surveyors to the British Corporation.

The downton pump has been dispensed with for the present.

The anchors and cables have been examined by the British Corporation Surveyors and the Certificates endorsed by them, but the marks on the anchors and the outer lengths of cables have again been examined and found in order and the equipment is as required by the rules for the figure "1".

It is submitted the vessel might be classed 100 A.1.

100 A.1. (Steel).

1 Dk. (Steel).

Cell DB 283' 736t. FPT 112t. APT 112t.

FK. 7 BH. pt.Cem. Lloyd's A.& C.P. P33', B98', F29'.

C.T.

[Signature]

[Signature]

26. 6. 19.



© 2021

Lloyd's Register
Foundation

Beats not advised

? really



© 2021

Lloyd's Register
Foundation

LEAD OFFICE
VINCENT S
GLASGOW.
GRAPHIC ADDI
CORTHY," GL
TELEPHONE
52 & 8153
If communicate
address
"THE SURV
Telegraphic
WORTHY," M
Telephone