

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

26th September, 1962.

C.
BN
Dear Sirs,

CLASSING LETTER.

2036 "TAMON MARU". As recommended except that according to the records in this Office the main engine fuel pumps and other auxiliary air receiver (two are noted as being on board), are outstanding for completion of the Continuous Survey of the machinery, and also the starting air pipes should be examined in accordance with Notice No.1 dated 25th January 1962.

It is concluded that the safety valves of both boilers were adjusted under steam, but I shall be glad to receive your confirmation regarding this matter, and also state the pressure to which the safety valves have been adjusted.

I shall be glad to learn what arrangements the Owners propose making to complete the Special Survey and Continuous Survey of the machinery.

Yours faithfully,

pro Clerk to the
Classification Committee.

The Surveyors,
SHIMONOSEKI.



© 2021

Lloyd's Register
Foundation

010079-010088-0204