

Chief Surveyors.....

Received from Chief Surveyors.....

NAME "TAMON MARU" REPORT Miami No. 343

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

of Survey Examination on account of ~~XXXXXX~~ contact damage.

NOTE D.

SUBJECT to indented shell plates H.8,9,10 & 17 with framing in way (p.s. from aft) being specially examined and dealt with as found necessary by the Special Survey and to counter plating with framing in way being specially examined and dealt with as found necessary by the next drydocking.

IN S.R.L. APPENDIX.

(Main structure partly of P.403 Steel)

NOTE:- The Owners request the internal examination of the lub. oil drain and lub. oil reserve D.B.tanks in E.R. be credited to the Special Survey (due 5,62).



© 2021

Lloyd's Register
Foundation
James
23/8/01