

9 SEP 1952

Received from Chief Ship Surveyor

THE Lady Alexandra.
British Columbia Coasting Service.

REPORT

Per.

No. 8766

Per

8762

ing Conditions of Class: Subject to cargo not being carried in
d until close ceiling is refitted.


at of Class (B) (~~As before or~~ None)

Present Survey: (Afloat and in dry dock)

Annual Survey: wear & tear repairs to inner bottom plating in No. 1 hold.
my repairs to collision damage.

ation: Submitted docking date 6.52 and notation
5 6.52 be assigned subject as above and to
ment repairs to indented fore-castle side & deck
if etc (p.s.) at the next drydocking.

Subject



© 2021

Lloyd's Register
Foundation

010089-010095-0103