

Boilers 200 lbs.

Boilers

Engineer Surveyor

NAME

'LADY ALEXANDRA'

REPORT

Ver.

No. 8762

2 E

9 SEP 1952

Received from Chief Engineer Surveyor

Works of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey, due 9.51

now held
partly

-NEW-

):-

~~pleted, and the following repairs carried out (due to-~~

ocking. Port screwshaft drawn and examined. A number of machinery parts examined, one tube renewed in forward boiler.

It is submitted the vessel is eligible to remain as classed, with

BkrS 6.52,

Port S 6.52.

as recommended.

tation of



8. 9. 52.

Lloyd's Register
Foundation

010089-010095-0109

Starboard Main Engine - cylinders, pistons, valves and valve chests, crank pins