


22 JUN 1950

MEMORANDUM

n: **LLOYD'S REGISTER OF SHIPPING**, 71, FENCHURCH STREET,
LONDON, E.C.3.



The Surveyor(s) at **VANCOUVER.**

Date: **10th MAY 27 1950.**

el's Name: **S.S. "LADY ALEXANDRA".**

QUESTION.

ANSWER.

Date:— 6th June, 1950.

With reference to your report No.7957 and to the entry in the Special Reasons List, I shall be glad if you will ascertain and let me know what arrangements the Owners propose making for 30 fathoms of chain cable to be supplied.

LRP

The Owners' Superintendent states that this ship has never been equipped with more than 180 fathoms of 1-3/8" chain cable. It is submitted that this should be verified from British Corporation records as the vessel is employed only in the British Columbia Coastal Service.

LRP



© 2021

Lloyd's Register Foundation

010089-010095-0114