

25 JAN 1946

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "EMPIRE FORTH" REPORT Hul. No. 53232

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ex-German vessel was built in 1939.

The HULL Surveyors report the vessel placed in dry dock, bottom coated, and a GENERAL EXAMINATION held with a view to "Examined L.R." notation being assigned.

Repairs effected to fore peak tank top, stem, sheerstrake-plate etc. and to minor items.

A bower anchor on board now replaced by anchor of more suitable size, verified with certificate.

It would appear that a bower anchor and 45 fathoms of chain cable required to be supplied.

IT IS SUBMITTED the vessel is eligible to have record of docking survey 10.45 and the notation of "Examined L.R. 10.45" valid for 12 months as recommended assigned. (One bower anchor and 45 fathoms of chain cable to supply).

10.45 Hul. (subject.)

"Examined L.R. 10.45"



16.1.46

J.C.D. 2021

Lloyd's Register  
Foundation

010150-010162-0197