

1

GB Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "OCEAN EAGLE" REPORT Jck. No. 2044

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey. Docking: S.R.L. ~~When due~~NOTED.

Subject to indented side shell plating (p.s. amids)
also bottom shell plates A.6, B.5 & 6, D.4, G.13 & 14 and H.12,
J.13 (p.s.) and framing etc. in way of No.6 port tank being
examined and dealt with as necessary at the next drydocking.

OFFICE NOTE

Structural arrangements in order - 21.2.55.

IN L.O.E.

(Main structure partly of P.403 Steel).

AM.
9.10.57



© 2020

Lloyd's Register
Foundation

010200-010207-0022