

010219 - 010228 - 014

9 OCT 1930

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel Sc. "MARVOLITE" Report Lon. No. 95590a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Age of Survey \_\_\_\_\_ When due \_\_\_\_\_

The S.S. No.1 became due 7.30.

In reply to enquiry the Owners now state they wish to discontinue the classification of the vessel with this Society.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2021

Lloyd's Register  
Foundation

*[Handwritten signatures and initials over the Lloyd's Register logo and text]*

M. of  
on  
on, 1  
s, &c.  
was  
sed  
letter  
of  
e if n  
s, bo  
ngth  
Varps  
i Ran  
giste  
lased