

010219-010228-0268

26 OCT 1964

Ship's name SS "AKAMAS"

Port Rotterdam

No. 59107

Last survey date 4/9/64

Class is subject to ① M.E. bedplate (Mistake 1/63) being examined by 11/64,

- ② Propeller & O.T. & sea valves being examined at next V.D.,
 & ③ Wasted CE stays in starb. boiler and defective smoke & stay tubes and air-heater tubes (pugged & thin) in all 3 boilers being renewed by 9/64 (4 nos.).

TSCA. (due 6/64) was held. V.D., Repairs.
 MBS. (due 9/63) commenced 11/63, was advanced.

SOL. Item ②, Prop. sea valves, was dealt with & to be deleted.
 Item ③ Boilers. Centre boiler retained.
 starb. side - P. & Centre smoke boxes retained.

The Surveyor recommends that the wasted stay and plain tubes in Port boiler and starboard base of starboard boiler and air-heater tubes of all three boilers (thin) be renewed by 10/64 (1 nos.).

Smooch, found cracked 4" long circ. at forward end of taper & several cracks at side of keelson, and replaced by spar. Spar shaft (rust) skinned & taper crack - detected. Stern bush (cracked) removed.

It is submitted that the vessel WILL BE eligible for the record TSCA 9/64 NOW & MBS. 11/63 when the survey has been completed, by completion of

the subject item in boilers,

subject as above in M.E. bedplate, as now amended in boiler repairs,

without condition in prop. & sea valves.

W.D. 1.0% (Rounded @ 6.7%)
 23/10/64.

Surveyor was informed that it is owner's intention to change the ABS classification at Piraeus in 10/64.