

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

31st December, 1963.

Telephone: ROYal 9166
Telex No.: 24305

Yr.Ref. DGG/DM

C.
RLT/DET

Dear Sirs,

Steamer "AKAMAS"

Referring to your letter dated 21st November, a report has now been received from the Society's Surveyor at Havana.

During this survey, the Metalock repairs to the main engine bedplate were examined but it was recommended that a further examination should be made before the end of November 1964, and class has been continued subject, inter alia, to this matter receiving attention by that time.

The Main Boiler Survey was also commenced by the examination of the starboard boiler and in view of the condition of the boiler at that time, it was recommended that it be again examined on the ship's arrival in Japan at the end of the present voyage.

To complete this survey, the port and centre boilers require to be examined in their entirety, safety valves of all boilers to be adjusted under steam, oil burning system and remote controls to be examined and repairs effected to combustion chamber stays and air heater tubes of the starboard boiler.

Yours faithfully,

Deputy Clerk to the
Classification Committee

Messrs. N. & J. Vlassopoulos Ltd.,
Bevis Marks House,
Bevis Marks,
LONDON, E.C.3.

© 2021

Lloyd's Register
Foundation

010219- 010228- 0320