

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

14th March, 1963

C
DHGK/BDF

Dear Sirs,

S.S. "AKAMAS"

When this ship was at Falmouth in January/
February last, the main engine bedplate was found
cracked at the port forward corner through No. 1
bearing transverse.

Some metalock repairs were carried out, but
it was recommended that these repairs should be
examined before the end of July, 1963 and class
has been continued subject to this matter being
dealt with by the time stated.

Yours faithfully,

Deputy Clerk to the
Classification Committee

Messrs. N. & J. Vlassopoulos Ltd.,
Bevis Marks House,
Bevis Marks,
LONDON, E.C.3.



© 2021

Lloyd's Register
Foundation

010219- 010228 - 0334