

1E

12 APR 1933

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME ISMV "PROCYON"

Rpt. Malmo No. 1191

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92).

Kind of Engine OIL ENGINES
4 SCSEA. 16 cy.

If Boilers fitted with forced draught

✓

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of approved type

No


This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  LMC 3.33.


2 DB - 171 lbs.

CL.

ELEC. LIGHT.

NHP. 865.





© 2021

Lloyd's Register Foundation

010236-010245-0047



© 2021
Lloyd's Register
Foundation

Handwritten signature

15.7.51

Handwritten initials

245 882

TRIP 245

171-20

CE:Σ CMΔ ❀

basele of of eldi

at the battin... and the... and...

egyt bevoiqe

It... and...

It... and...

19.09.

23MMJ Δ 19

WORDOY

JOB

1911.08

Received from...

JE

For the information of the Committee only.