

COPY

LLOYD'S REGISTER OF SHIPPING



Port HONG KONG.

27th September, 1961.

This is to Certify that I have

Main Boilers
 Surveyed the ~~Machinery~~ of the S.S. "AMELIA", 2839 tons gross,
of Panama, whilst lying afloat at this Port,
 and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will **Recommend** that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
M.B.S. 9,61, when the Survey has been completed,
 and that her Machinery Classification Record be continued in the Book.


Parts now examined:-

---(C.S. Items only)---

To Complete the Boiler Survey:-

Safety valves on both boilers to be adjusted under steam.
 The oil fuel burning and the fire extinguishing
 arrangements within machinery and boiler spaces to be
 generally examined and tested under working conditions.

(Signed)



John Manson
 Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021
 Lloyd's Register
 Foundation
 010246040253+0076