

Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers?

010276-010282-0033

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

Adelma

REPORT

HKy.

No. *12292*

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS

This Survey, due *10/53* now held *scrapped* ~~now~~
minor partly ~~completed~~, and the following repairs carried out (due to *wear & tear*):—

© 2021

Lloyd's Register
Foundation

It is submitted the vessel is eligible to remain as classed, with

tation of *MSR*1254 Mr. S. 1254*
S. 12.54 SPS 1254

as recommended *fresh paper have*
been of repd recommended it is concluded
in tested in accordance with Rules although not stated in Rsl.

condition & eligible, in my opinion, to be continued as classed with fresh record