

Received from Chief Ship Surveyor **22 OCT 1952**

NAME

"OTTERHOUND"

REPORT

St. J.

No. 1766

Existing Conditions of Class: Subject to indented side shell plating (p & s) being dealt with by next Special Survey and to a bower anchor and 15 fathoms chain cable being supplied at the earliest opportunity.

ACTION is DEFERRED for Special Survey by 12,52.

Postponement of Class (B) (As before ~~or None~~)

Postponement due: Postponement of SPECIAL SURVEY (D) (due 12,51) until 12,52 previously approved.

Condition of Present Survey: (~~Afloat and~~ in dry dock) Permanent - deferred repairs to damage caused by striking a submerged object.

Special Features:

NONE

Permit Certificate in order (~~Yes No None~~)

Outstanding: (If any for S.S. or A.S.)

All items of SPECIAL SURVEY.

to be <sup>held</sup> completed by: 12,52.


Recommendation:

SUBMITTED record of docking 8,52 be assigned as recommended SUBJECT as above and to indented keel and bottom plating (p.s.a.) being dealt with by the Special Survey and to the sternframe sole-piece (E.W.8,52) being specially examined at the next drydocking but FURTHER ACTION be DEFERRED for Special Survey by 12,52.

8,52 St. J. Subject.

ENDORSEMENT OF CLASS (B).

Indents in side shell plating (p & s).



© 2021

Lloyd's Register  
Foundation

010296-010282-0080