

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

6th January, 1919.

Dear Sir,

I enclose herewith for your information, a photo print of a circulating arrangement which is stated to have been fitted in the donkey boiler of the S.S. "ANGLO SAXON", No.984 in the Register Book.

No Report has been received at this Office of the fitting of any circulating pipes in this boiler, and the Owners' Superintendent states that he was not aware of the arrangement having been supplied until the steamer's arrival at Hull from New York recently.

In view of the Boiler being ^{fed} fitted with salt water, and the impossibility of cleaning or internally examining the pipes in question, it is considered that they are a source of danger and cannot be approved, and the Society's Surveyors at Hull have been requested to arrange for the pipes to be removed.

The Secretary,
NEW YORK.

I am, Dear Sir,
Yours faithfully,

Secretary.



© 2021

Lloyd's Register
Foundation

010276-010282-0194