

besides being detailed in the body of the report, should be separated from Repairs due to other causes; and dates and initials of any letters respecting this case.

S.S. Sld 701 27

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

3m, 11.24.

POSTPONED SURVEYS.

Case of the Steel S.S. "POLMINA"

No 30435 in Reg. Bk. 896/434 tons, Built 1917-2
Classed 100871 Owners King & Co (Cardiff) Ltd.,
3.24 T. 11 23 Port of Registry London
No 1-22 Thine 3.22 P. 9.24

Survey Due Special Survey No.2 due 2,25.
Boiler Survey due 9,25.
Screwshaft survey due 11,25.

In March last the Owners stated this vessel was laid up at Cardiff and that they desired to be allowed the year of grace for the Special Survey No.2. In the circumstances the Committee agreed to this arrangement.

In reply to a Notice in regard to the Boiler Survey the Owners state the vessel is laid up, but this inspection will receive attention before she is chartered for further business. They add they note the screwshaft becomes due for survey at the end of the present month and that they are accordingly advising their Superintendent Engineer, who will give this matter his attention.

Committee's Minute TUES. 3 NOV 1925

Decision Deferred

Submitted advice deferred

[Signature]

[Signature]
2-11-25



© 2021

Lloyd's Register Foundation

010283-010288-0025

Travelling Expenses (if chargeable).....

Committee's Minute

TUES. 29 DEC 1925

FRI. 26 MAR 1926

Engineer Surveyor to Lloyd's Register

er steam #180
er steam?
?
?
?
t the after en
ciently lubricat
nd of {
ated ? }
l,
e.
leaving
lowing
collars,
liary p
; Throu
sure p
vessel
quent upon th
11, B.&M.S. 9,1
em au
d in i