

offered his services for this purpose, and why they were declined *Yes, not req'd*
Was a damage report made by anyone else? If so, by whom? *Sur to Lou Sal Assocⁿ*
Surveyor personally go inside each Main Boiler separately and make

D.24.

POSTPONED SURVEYS.

Case of the Steel S.S. "POLMINA"

50277 in Reg. Bk. *896/434* tons, Built *1917-2mo.*
Classed *F100A1* Owners *Haig Shipping Co. Ltd.*
3,24
No 1-22: *FHMC 3,22* Port of Registry *London*
BS9, 24
TS11, 23

Survey Due Special Survey No.2 due 2, 25.

The Owners state this vessel is at present laid up at Cardiff and that they desire to be allowed the year of grace for the above survey.

Submitted for approval
MS.
16/3/25.

Committee's Minute TUES. 17 MAR 1925

Decision *Approved*

MS



© 2021

Lloyd's Register Foundation

Travelling Expenses (if chargeable)..... £

Committee's Minute TUES. 29 DEC 1925

FRI. 26 MAR 1925 TUES. 12 JUN 1925

d under steam
d under steam
Boiler?
Boiler?
Boiler?
tted at the a
ag efficiently l
fter end of }
lubricated ? }
ded,
life
ter bear
Follow
d coll
iliar
ves, h
ui.
pressu
this ves
, consequ
B.S. 9,11, B.&
t remu
tered

010285-010288-0029
James Murdoch
Engineer Surveyor to Lloyd's