


COPY

LLOYD'S REGISTER OF SHIPPING



Port Ipswich

20th October, 1959

This is to Certify that I have

Surveyed the Machinery of the S.S. "ERINIO" ex "OAKLEY" 7140 tons gross of Desrut whilst afloat in the River Stour off Harwich on the 14th October 1959, for commencement of Engine Special Survey and Main Boiler Survey,


and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book B.S. (with suitable date) and M.B.S. 10.59 when the Surveys have been completed, and that her Machinery Classification Record be continued in the Book, subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:

(C.S. Items only)

To complete the B.S.:— Inboard & outboard feed pump buckets to be renewed. All Rule requirements to be complied with except:— Inboard & outboard generator engines. Fan engine condenser circulating pump and engine. Inboard and outboard feed pumps.

To Complete for record of MBS. 10.59 All main boilers to be examined under steam, their safety valves adjusted, and oil burning system and remote controls examined under working conditions.


 Engineer Surveyor to (Lloyd's Register).

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)