

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760.


RE-CONSTITUTED 1834.

Certificate of Class

Twin Screw Steamer "PATHFINDER"
Official Number — Port of Registry Lagos
Owners Government of Nigeria.
Builders, and where and when built J. Samuel White & Co., Ltd., East Cowes, I.O.W.,
April, 1954.

REGISTERED PARTICULARS.

Length	154.45 feet	Tonnage, Gross	543.85
Breadth	27.65 feet	Ditto under Deck	363.03
Depth	11.45 feet	Ditto Net	197.68


This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 28th June, 1954 at Lagos in a fit and efficient condition as is prescribed by the Society's Rules and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 For Nigerian Coasting Service.
Fitted for oil fuel 4,54 flash point above 150°F.
subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	2 feet 1½ inches (T).	Winter	} — feet — inches (WNA).
Summer	2 feet 3 inches (S).	North Atlantic	
Winter	— feet — inches (W).	Allowance for fresh water for all freeboards	} 2½ inches

Witness my hand,

W. J. Ferguson
Secretary,


Chairman.

71, Fenchurch Street, London, E.C.3. 10th August, 1954.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register
Foundation

010289-010293-0160