

E X T R A C T FROM MSL. CLASSING LETTER D'D.28th Jan.1958.

SSO BRETAGNE" 12313 - As recommended, except that a notation of TS 11,57 has been assigned.

It is concluded that there are three bower anchors on board, not two as reported by you, but your confirmation is desired.



© 2021

Lloyd's Register
Foundation

010289 - 010293 - 0220