

"ESSO BRETAGNE"


It is noted that the Surveyor has recommended a fresh record for the machinery, but the examination of the following items has not been referred to in his report, namely:-

Coolers for the main alternator and propelling motor, ✓
Exciters for the main alternator, ✓
Electric propelling equipment (contactors, circuit breakers, ✓
cables etc.) ✓
Emergency oil engine set, ✓
Auxiliary condenser, ✓
Auxiliary circulating pump, ✓
Oil feed pump, ✓ *? Aux Feed P. Item*
Extraction pumps, ✓
Ballast, lubricating oil and oil fuel transfer pumps, ✓
Oil fuel installation, ✓
Combustion control air compressor and receiver, ✓
Auxiliary electrical equipment. ✓

IT IS SUBMITTED the Surveyor should be requested to confirm whether the survey has been completely held in this respect.

for
19/6/53
SM
✓

28.4.53.



© 2021

Lloyd's Register
Foundation

010289-010243-0277