

they were declined? Yes Not required

Was a damage report made by anyone else? If so, by whom?

HONE: No. 173 SUNDERLAND.



# Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 16th. February 1925.

Dear Sir,

In reply to your letter of the 14th instant, I have to inform you that the inner surface of the bottom plating in way of the dry tank under the boilers in the steamer "QUERIMBA", First Entry Report No. 29014, is covered with portland cement.

I am, Dear Sir,

Yours faithfully,

*T Shaw.*

For the Surveyors,

The Secretary,  
LONDON.



© 2021

Lloyd's Register  
Foundation

010294-010299-0186

010294-010299-0186  
Surveyor to Lloyd's Register



Referred to the Chief Ship Surveyor.

7am.

17 FEB 1915

*[Signature]*

17.2.15

*[Signature]*

THE SECRETARY,  
LONDON.

RECEIVED 17 FEB 1915

RECEIVED 17 FEB 1915

RECEIVED 17 FEB 1915

RECEIVED 17 FEB 1915

RECEIVED 17 FEB 1915

© 2021

Lloyd's Register  
Foundation