

...carried through the bunkers none

How are they protected —

\* S. S. Lucia "

{Mague 12.  
Tri. 5362.  
" 5363.

During to the propeller striking a  
mooring buoy the screw shaft has  
been examined and the propeller  
renewed.

It is submitted that  
this vessel is eligible for  
THE RECORD. F. L. M. C. - 3.22. F. D. C. L.  
Fitted for Oil Fuel, 3.22, F.P. above 150°F.



© 2021

And Lloyd's Register  
Foundation

010294-010291-0238

meter of tubes 3.5" Pitch of tubes 4" x 4.2" Material of tube plates Steel Thickness: Front .94 Back .78"